# Oil Field Environmental Incident Summary

Responsible Party: ONEOK Rockies Midstream

Well Operator: Well Name:

Field Name: Well File #:

Date Incident: 7/30/2014 Time Incident: 17:00 Facility ID Number:

County: MCKENZIE Twp: 150 Rng: 100 Sec: 32 Qtr: SE SW

Location Description: Head west out of Arnegard, ND on Highway 85 to McKenzie County Road 17

and take a right. Head north for approximately 2 miles and take a right on 30th Street (County Road 20). Travel 1/4 mile east and the site will be north

of the gravel road.

Submitted By: Mitch Anderson Received By:

Contact Person: Mitch Anderson

2700 Lincoln Avenue SE Sidney, MT 59270

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile
Distance Nearest Water Well: 1 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Pipeline ROW Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

**Brine** 

Other 2 Barrels 2 Barrels

**Description of Other Released Contaminant:** 

**Natural Gas Liquids (Condensates)** 

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

There were no immediate hazards to public health nor injuries to workers.

Areal Extent:

The aerosolized mist was broadcast onto adjacent topsoil approximately 150'L x 75'W x 1/16"D.

## Potential Environmental Impacts:

There were no environmental impacts to groundwater or surface waters.

### Action Taken or Planned:

The pipeline was isolated and allowed to de-pressurize so repairs to the pipe can be implemented.

Wastes Disposal Location: Contaminated soils above the action levels will be transported off-site to

a licensed landfill.

Agencies Involved: McKenzie County LEPC Director

# **Updates**

Date: 7/31/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release of natural gas liquidis from a pipeline leak, sprayed adjacent land. Follow-up is necessary.

Date: 8/7/2014 Status: Inspection Author: Martin, Russell

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

Pipeline hit during delineation sampling of Statoil saltwater spill (see incident # 20140725105423). Four rolloffs were filled with impacted material, and one pile of impacted soil still on site next to excavation will also be removed for disposal. Recommended a liner be placed under the impacted soil; cleanup personnel will be excavating 3 inches below the pile to remove any clean soil now impacted by the pile placed on it. Spray from line hit went southeast; vegetation has been removed in this direction. Vegetation further to the southeast shows no visible impact.

Date: 8/19/2015 Status: Inspection Author: Wax, Pete

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

On site 17:20 clear, 73 degrees. Visually inspected the pipeline row. No evidence of impact remains in the small grain field or road ditch. Off site 17:45.